

NUMBER: 08-012-11

GROUP: Electrical

DATE: March 15, 2011

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL 11-025. ALL APPLICABLE SOLD AND UN-SOLD VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Decklid Can Be Opened Without The Key Fob Being In The Proximity Of The Vehicle

OVERVIEW:

This Bulletin involves adding Security Alarm (sales code LSA) and reconfiguring the vehicle.

MODELS:

2011 (LC) Challenger

NOTE: This bulletin applies to vehicles built between November 24, 2010 (MDH 1124XX) and January 27, 2011 (MDH 0127XX) equipped with Keyless Go (sales code GX4) and Remote Keyless Entry (sales code GXD) without Security Alarm (sales code LSA).

SYMPTOM/CONDITION:

On some vehicles the decklid / trunk can be opened from outside the vehicle without a key fob being present, by pressing the trunk passive entry button.

DIAGNOSIS:

If the customer experiences the Symptom/Condition perform the Repair Procedure.

REPAIR PROCEDURE:

- 1. Run a VIP report for the vehicle and determine if the LSA sales code is present under the Dealer Installed Equipment section of the report.
- 2. Is the LSA sales code present?
 - a. Yes >> Continue to Step #3
 - b. No >>> Create a trouble ticket referencing this bulletin and indicating that the LSA sales code will need to be added to the vehicle in question.
- 3. Using wiTECH, reconfigure the vehicle to add the LSA sales code to the vehicle. This routine is available under the 'Diagnostic Procedures' tab found on the home, 'Vehicle View', page of wiTECH.

08-012-11 -2-

4. Using wiTECH clear any DTCs which may have been set.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
08-89-01-93	Verify LSA Sales Code and Reconfigure Vehicle(B)	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action