

NUMBER:	08-036-11
GROUP:	Electrical
DATE:	June 29, 2011

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

SUBJECT:

iPod and iPhone Compatibility Issues

OVERVIEW:

This Bulletin involves performing a USB service flash of the Hands Free Module (HFM).

MODELS:

2011	(LC)	Challenger
2011	(MK)	Compass / Patriot
2011	(PM)	Caliber
2011	(WK)	Grand Cherokee
2011	(W2)	Grand Cherokee
2011	(WD)	Durango
2011	(KK)	Liberty
2011	(K1)	Cherokee
2011	(KA)	Nitro
2011	(JS)	Avenger / 200
2011	(DS)	1500 Pickup
2011	(DJ)	2500 Pickup
2011	(D2)	3500 Pickup
2011	(DD)	3500 Cab Chassis
2011	(DP)	4500/5500 Cab Chassis
2011	(DX)	1500 Pickup (Mexico)
2011	(JK)	Wrangler
2011	(J3)	Wrangler (CKD)
2011	(RT)	Grand Caravan / Town & Country

NOTE: This bulletin applies to vehicles built prior to April 18, 2011 (MDH 0418XX) equipped with UCONNECT VOICE COMMAND W/BLUETOOTH (sales code RSP, RSQ for international) and without MEDIA CENTER 730N CD/DVD/MP3/HDD/NAV (sales code RER or RHR) or MEDIA CENTER 735N CD/DVD/HDD/NAV (sales code REW or RHW) or MEDIA CENTER 731N CD/DVD/HDD/NAV (sales code REP) or AM/FM CD MP3 NAV RADIO - ROW (sales code RHP).

SYMPTOM/CONDITION:

The customer may experience the following:

- The message "connecting to device" is displayed on Apple iTouch, iPod, or iPhone when connected to the vehicle USB port, but the device will not sync to the HFM to play audio.
- iPhone 4 audio will drop out and skip during a streaming audio session.

DIAGNOSIS:

- 1. Using wiTECH, determine the HFM part number. The HFM part number can be found under Module Information for the HFM.
- Is the HFM Part number one of the following: NAFTA: 05064634AF/AG 05064635AF/AG 05064735AF/AG 05064870AF/AG BUX: 05064728AF/AG 05064730AF/AG 05064740AF/AG 05064871AF/AG?
 - a. Yes >> Perform the Repair Procedure.

b. No >>> This service bulletin does not apply. Further diagnostics may be required. If the customer describes the symptom, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1(AR)	82212160	USB Cable (KA/KK/K1 Only)
1(AR)	Dealer Supplied	USB Portable Flash Drive / Memory Stick (256 Mb or larger, formatted for Windows)

NOTE: One USB Cable P/N 82212160 may be used to service multiple vehicles.

REPAIR PROCEDURE:

HFM Remote USB Port Connector Location Table

Vehicle Family.	UCI-USB Connector Location	
LC	USB port connection located in center console; forward-most side. Connection illuminates when ignition/ Accy is ON	
PM / MK	USB port connection located in passenger glove compartment; Top-right corner, Above glove compartment when OPEN. Connection illuminates when ignition/ Accy is ON	
WK / WD	USB port connection located in center console, backside of Top Tray. Connection illuminates when ignition/ Accy. is ON	
JS	USB port connection located below HVAC controls;. Connection illuminates when ignition/ Accy. is ON	
JK	USB port connection located in center console; forward-most side. Connection illuminates when ignition/ Accy. is ON	
RT	USB port connection located in TOP passenger glove compartment; Left Side. Connection illuminates when ignition/ Accy. is ON	
RAM Trucks	USB port connection located in passenger glove compartment. Connection illuminates when ignition/ Accy. is ON	
KA / KK / K1	NOT EQUIPPED with USB Connection; See Special instructions	

Prepare USB Memory Stick

- NOTE: Preparation of the USB memory stick involves using the wiTECH flash framework to copy a proprietary module flash application to a USB memory stick. The USB memory stick is then used to flash update the Hands Free Module
- 1. Verify that the Hands Free Module is functioning as designed. If DTC's are present, record them on the repair order and repair as necessary before proceeding further.
- 2. Proceed with the wiTECH Diagnostic Application to reflash the HFM (Fig. 1). Help using the wiTECH Diagnostic Application for flashing Hands Free Module is made available through the wiTECH Diagnostic Application. For instructions select the "HELP" tab on upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.

Utilities Repo	c Application - 11.0 orts Monitors	Preferences Ab	ut Help	.8
UUIIURS Meps	orts mornitors	Preiler ences Ab	ar meib	Search
4 . 54	HEM N	liow		Service Information
+ <i>P</i>			ions and information for the selected ECU.	
	and the second second	Flash Data	DTCs Actuators System Tests Misc	Functions ECU Details
	2000	Flash Data	DICS Actuators System lesis Misc	Punctions ECO Decails
		Current ECU Flas	Number: 68140636AA	
2000		Battery: 🛤 1	78 volts	
			or dick on appropriate button to update ECU. Click on column head	ding to surt table.
		New Part Number	Description	
FM Overview		6814063644	2011 RT KA HEN DOMESTIC	
me:	Hands Free			
1991	Module(cell			
ish Part Number:	phone) 68140636AA			
a Type:	CAN RIS			
ardware Version:	13.04			
ftware Version: IC Count:	43.01.40			
c cours.	°.			
		A A		
		Note: Please review connected vehicle. NOT function proper	all available service documentation (5B's, RRT's, Reca a flash is not applicable to the connected vehicle, it /t	If s) to ensure the available flash applies to the could damage the ECU or cause the vehicle system t
Knowledge Base Artis	des 📲	Desiar Code: 99870		Disconnect warnings 0 th

Fig. 1 wiTECH Flash Application

3. The Flash Warning Dialog will appear(Fig. 2). Click on OK to acknowledge the warning.




Fig. 2 wiTECH Flash Warning Dialog

4. The Download Progress Dialog will appear (Fig. 3). Click on OK after progress has reached 100%.

writeCH Diagnostic Application - 11.03.64 Utilities Reports Monitors Pre	ierences About Help	
ECU Flash: HFM - 68140636AA		P
Flash Dov	nload Progress	
01.4		
HFX		
Nam		
Plani Bran Hann Suith DTC		
erc		
Prograss: 15%		
Cancel	10	

Fig. 3 wiTECH Download Progress Dialog

5. The Supplier Application Warning Dialog will appear (Fig. 4). Click on OK to acknowledge the warning.




Fig. 4 Supplier Application Warning Dialog

6. A scrollable Process Description Dialog will appear (Fig. 5) and (Fig. 6). Insert the dealer supplied USB memory stick into the first USB port of the wiTECH computer at this time, ensure that no other USB memory sticks are installed, and click on OK to acknowledge the instructions.



Fig. 5 Process Description - Top Of Scrollable Dialog




Fig. 6 Process Description - Bottom Of Scrollable Dialog

- 7. The Successful Completion Dialog will appear once the update files have been copied to the USB memory stick. Click on OK to acknowledge successful creation of the update USB.
- 8. Remove the update USB from the wiTECH computer for later use.




Fig. 7 Successful Completion Dialog

Perform Software Reflash

- NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.
- NOTE: In the event of a reflash failure the system will respond with an audio prompt indicating "Digital Signature not recognized" or USB Mass Storage device not compatible". If this should occur, download the flash to the USB Flash Drive using a different USB port on the computer. If this does not resolve the issue use another brand of flash drive.
- CAUTION: Damage to the HFM may occur! Do not interrupt vehicle power, cycle ignition, or remove the USB memory stick while performing software reflash. If the flash is interrupted and an audible prompt is NOT heard after pressing the radio's phone button (with the radio volume set at 3/4 volume or higher, the HFM module will need to be replaced. If the flash is interrupted and an audible prompt IS heard after pressing the radio's phone button the flash can be reattempted.
- 1. Locate the HFM Remote USB Port using the HFM Remote USB Port Connector Location Table (This is **NOT** the same as the USB port located on the radio).
- 2. Access the HFM USB Connector (Go to Special Instruction for KA/KK/K1 only).
- 3. Insert the HFM software update USB Memory Stick into the Remote USB Port Connector.
- 4. Sit in the passenger seat and close all doors and windows.
- 5. Press and release the radio's u-Connect Phone button and, following the HFM verification prompt, say "Set-up, Software Update". The system will respond with an audio prompt stating: "Starting Software Update, Please Wait".
- 6. The audio prompt will be followed by periodic beeps for approximately 20 minutes. After the periodic beeps end the radio will exit re-flash mode and return to the last radio mode.

NOTE: Do not remove the USB memory stick at this point.

7. Wait one additional minute for the HFM to complete the update and reset.

Verify Software Reflash

- 1. Press and release the phone button.
- 2. Quickly turn the radio volume control knob to above 3/4 of maximum volume and leave it there.
- Did the vehicle audio system play any of the following verification prompts: "UConnect Ready ... beep", "Ready ... beep", or just an audible "beep"?
 a. YES >>> Proceed to Step #4.
 - b. NO >>>> Proceed to Step #4.
- 4. Press and release the phone button to end the session.
- 5. Using wiTECH, determine the HFM part number. The HFM part number can be found under Module Information for the HFM.
- 6. Is the HFM Part number one of the following: 68140645AA, 68140646AA, 68140634AA, 68140636AA, ?

a. Yes >>> Proceed to Step #8.

b. No >>> Proceed to Step #7.

- 7. Have you attempted the Flash Procedure at least twice previously?
 a. YES >>> This service bulletin does not apply. Further diagnostics may be required.
 b. NO >>>> Reattempt the 'Perform Software Reflash' procedure.
- 8. Remove and properly store the USB Memory Stick.
- 9. Using WiTECH clear any faults which may have been set during the reflash procedure.
- 10. KA / KK vehicles only, return to the Special Instructions Step #6.

Special Instructions (KA / KK / K1 Only)

The 2011 KA (Nitro), KK (Liberty), and K1 (Cherokee) **are not equipped with a remote USB port.** They have the capability of being upgraded by using the MOPAR PN# 82212160 (USB Harness) for the reflash process.

The HFM Module on the KA / KK is located on the right rear side (passenger's side on left hand drive vehicles also), and behind the audio system's subwoofer enclosure.

- Access the HFM Module by following steps 1 through 4 in DealerConnect / TechCONNECT> Group 08 - Electrical> 8T - Navigation/Telecommunications> MODULE, Hands Free (HFM)> Removal — REMOVAL.
- 2. Do **NOT** disconnect the electrical connectors from the HFM.
- 3. Connect the USB harness (PN# 82212160) as shown in (Fig. 8).
- 4. Reconnect the battery.
- 5. Return to the Perform Software Reflash Procedure Step #3.




Fig. 8 USB Harness Connection

1 - USB harness PN# 82212160

- 6. Disconnect and isolate the battery negative cable.
- Reinstall HFM Module by following steps 2 through 5 in DealerConnect / TechCONNECT> Group 08 - Electrical> 8T - Navigation/Telecommunications> MODULE, Hands Free (HFM)> Installation — INSTALLATION.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
18-19-63-95	Diagnosis Only - HFM Part Number (C)	0.2 Hrs.
18-19-63-96	Diagnose and Flash Reprogram HFM Module (C)	0.5 Hrs.
18-19-63-97	Diagnose and Flash Reprogram HFM Module - KA / KK / K1 Only (C)	0.9 Hrs.

FAILURE CODE:

FM	Flash Module
----	--------------