

April 29, 2009

TO: ALL DODGE DEALERS

FROM: GLOBAL SERVICE

SUBJECT: RAPID RESPONSE TRANSMITTAL/SERVICE ACTION #08-079 REV. A
Right Outside Rearview Mirror Loose

THIS IS A REVISION TO RAPID RESPONSE TRANSMITTAL #08-079 DATED OCTOBER 9, 2008 WHICH SHOULD BE REMOVED FROM YOUR FILES. HEATED MIRRORS AND SRT MODELS HAVE BEEN ADDED. ALL CHANGES ARE HIGHLIGHTED WITH ** ASTERISKS ****.**

INVOLVED VEHICLES:

2009 (LC) Challenger

NOTE: This Service Action affects both sold and unsold vehicles.

NOTE: This Service Action should not be a transportation claim.

NOTE: The VIN List is available on DealerCONNECT for all affected dealers. The VIN List has been inserted in the Service Tab under Rapid Response Transmittals. The dealers receiving the Rapid Response Transmittal Service Action are the "Ship To" dealers and the VIN's listed are specific to their dealership. All involved vehicles will be loaded into the VIP system.

NOTE: This should be a top priority and be completed prior to sale to avoid suspect vehicles being delivered to customers.

DISCUSSION:

A number of vehicles equipped with foldaway power mirrors (sales code – GTN ****or GUK****) were shipped with a loose right outside rearview mirror that will not stay in a normal position. Dealers are required to replace the right outside rearview mirror.

PARTS REQUIRED:

| Qty. | Part No. | Description |
|-------------|-----------------|--|
| (AR) 1 | 1GD72FDTAD | Mirror, Outside, Rearview, Right, with (GTN) - Hemi Orange |
| (AR) 1 | 1GD72FDTAD | Mirror, Outside, Rearview, Right, with (GTN) - Dark Titanium |
| (AR) 1 | 1GD72AXRAD | Mirror, Outside, Rearview, Right, with (GTN) - Black |
| (AR) 1 | 1GD72ARHAD | Mirror, Outside, Rearview, Right, with (GTN) - Inferno Red |
| (AR) 1 | 1GD72WS2AD | Mirror, Outside, Rearview, Right, with (GTN) - Bright Silver |
| (AR) 1 | 1GD72SW1AD | Mirror, Outside, Rearview, Right, with (GTN) - Stone White |
| (AR) 1 | 1GD72ZR3AD | Mirror, Outside, Rearview, Right, with (GTN) – Torred |

PARTS REQUIRED (continued):

| | | | | |
|----|------|---|------------|--|
| ** | (AR) | 1 | 1GE18FLCAD | Mirror, Outside, Rearview, Right, with (GUK) - Hemi Orange** |
| ** | (AR) | 1 | 1GE18FDTAD | Mirror, Outside, Rearview, Right, with (GUK) - Dark Titanium** |
| ** | (AR) | 1 | 1GE18AXRAD | Mirror, Outside, Rearview, Right, with (GUK) - Black** |
| ** | (AR) | 1 | 1GE18ARHAD | Mirror, Outside, Rearview, Right, with (GUK) - Inferno Red** |
| ** | (AR) | 1 | 1GE18WS2AD | Mirror, Outside, Rearview, Right, with (GUK) - Bright Silver** |
| ** | (AR) | 1 | 1GE18SW1AD | Mirror, Outside, Rearview, Right, with (GUK) - Stone White** |
| ** | (AR) | 1 | 1GE18ZR3AD | Mirror, Outside, Rearview, Right, with (GUK) - Torred** |
| ** | (AR) | 1 | 1GE18GBSAD | Mirror, Outside, Rearview, Right, with (GUK) - Blue** |

REPAIR PROCEDURE:

1. Replace the right outside rearview mirror. Follow the detailed service procedures available in DealerCONNECT/TechCONNECT, under: Service Info > Group 23 – Body > Exterior > Mirror, Outside Rearview > Removal and Installation.
2. If the vehicle is equipped with Automatic Express Up power windows or Electronic Stability Program (ESP), review and perform the battery reconnection procedures as applicable. Follow the detailed service procedures available in DealerCONNECT/TechCONNECT, under: Service Info > Group 08 – Electrical > 8F – Engine Systems > Battery System > Standard Procedure > Battery Reconnection.

POLICY: Reimbursable within the provisions of the warranty.

NOTE: USE OF THE LABOR OPERATION INCLUDED WITH THIS SERVICE ACTION ON VEHICLES OTHER THAN THOSE INVOLVED MAY BE SUBJECT TO CHARGE BACK.

TIME ALLOWANCE:

LABOR OPERATION NO:

| | | |
|-------------|---|----------|
| 23-04-21-90 | Mirror, Right Side Remote Power Outside Rearview – Replace (B). | 0.4 Hrs. |
| 23-04-21-91 | Optional Equipment – Calibrate ESP | 0.2 Hrs. |

FAILURE CODE: ZZ - Service Action

If you have any questions, contact your Business Center.