

December 22, 2008

**TO:** ALL CHRYSLER AND DODGE DEALERS

**FROM:** GLOBAL SERVICE

**SUBJECT:** RAPID RESPONSE TRANSMITTAL/SERVICE ACTION #08-098 REV. A  
Flash: Whistle Sound From Engine Compartment/Purge Solenoid

**INVOLVED VEHICLES:**

2008 - 2009 (LX/LE) 300/300C/ 300 Touring/Magnum/Charger

\*\*2009 (LC) Challenger\*\*

**THIS IS A REVISION TO RAPID RESPONSE TRANSMITTAL #08-098 DATED DECEMBER 18, 2008 AND INCLUDES 2009 LC MODELS. THE REVISIONS ARE HIGHLIGHTED WITH \*\*ASTERISKS\*\*.**

**NOTE:** This Rapid Response Transmittal affects unsold vehicles only.

**NOTE:** The VIN List is available on DealerCONNECT for all affected dealers. The VIN List has been inserted in the Service Tab under Rapid Response Transmittals. The dealers receiving the Rapid Response Transmittal Service Action are the "Ship To" dealers and the VIN's listed are specific to their dealership. All involved vehicles will be loaded into the VIP system.

**DISCUSSION:**

A number of vehicles have been shipped where after driving the vehicle some customers may complain of a whistle sound coming from the engine compartment while the vehicle is running. This condition is caused by the purge solenoid. A software change has been made to the current on the purge solenoid circuit which corrects the condition.

**REPAIR PROCEDURE:**

1. Following the procedures listed in Service Bulletin 18-036-08 REV. A dated December 3, 2008 – Reprogram the Powertrain Control Module (PCM)

**NOTE:** Due to the PCM programming procedure, a DTC will be set in other modules within the vehicle, if so equipped. Some DTC's may cause the MIL to illuminate. From the Home screen select System View. Then select All DTC's. Press Clear All Stored DTC's if there are any DTC's shown on the list.

**POLICY:** Reimbursable within the provisions of the warranty.

**NOTE: USE OF THE LABOR OPERATION INCLUDED WITH THIS SERVICE ACTION ON VEHICLES OTHER THAN THOSE INVOLVED MAY BE SUBJECT TO CHARGE BACK.**

**TIME ALLOWANCE:**

**LABOR OPERATION NO:**

18-19-06-E3	Module, Powertrain Control (PCM) – Reprogram with NAG 1 Transmission(B) 2009 Model Year (B)	0.4 Hrs.
18-19-06-E4	Module, Powertrain Control (PCM) – Reprogram with NAG 1 Transmission(B), Includes Initialize EGS52 2008 Model Year (B)	0.8 Hrs.
18-19-06-E5	Module, Powertrain Control (PCM) – Reprogram with 42RLE Transmission and Clear VLP counters (B)	0.4 Hrs.

**FAILURE CODE:**      ZZ - Service Action

If you have any questions, contact your Business Center.