

January 23, 2009

TO: ALL CHRYSLER AND DODGE DEALERS

FROM: GLOBAL SERVICE

SUBJECT: RAPID RESPONSE TRANSMITTAL/SERVICE ACTION #09-005
Right Camshaft Not Built To Proper Specification

INVOLVED VEHICLES:

2009 (JC) Journey
2009 (LC) Challenger
2009 (LX) 300/Magnum/Charger

NOTE: This Service Action applies to models equipped with a 3.5L engine (sales code EGF)

NOTE: This Service Action affects both sold and unsold vehicles.

NOTE: The VIN List is available on DealerCONNECT for all affected dealers. The VIN List has been inserted in the Service Tab under Rapid Response Transmittals. The dealers receiving the Rapid Response Transmittal Service Action are the "Ship To" dealers and the VIN's listed are specific to their dealership. All involved vehicles will be loaded into the VIP system.

NOTE: This should be a top priority and be completed prior to sale to avoid suspect vehicles being delivered to customers.

DISCUSSION:

A number of vehicles were built with a right camshaft that was not built to proper specification. Dealers are required to **Replace the right camshaft and cylinder head gasket.**

PARTS REQUIRED:

(1) 4792744AA Camshaft, Right
(1) 4792752AE Gasket, Cylinder Head

REPAIR PROCEDURE:

1. Replace the right camshaft (p/n 4792744AA), Following the procedures found in DealerCONNECT>TechCONNECT>Group 09 Engine, 3.5>Cylinder Head>Camshaft removal and installation.
2. Replace the cylinder head gasket (p/n 4792752AE).

POLICY: Reimbursable within the provisions of the warranty.

**NOTE: USE OF THE LABOR OPERATION INCLUDED WITH THIS SERVICE
ACTION ON VEHICLES OTHER THAN THOSE INVOLVED MAY BE
SUBJECT TO CHARGE BACK.**

TIME ALLOWANCE:

LABOR OPERATION NO:

09-05-01-90 Camshaft and Gasket, Cylinder Head,
Replace (B)

5.5 Hrs. JC Bodies
4.6 Hrs. LX/LC Bodies

FAILURE CODE: ZZ - Service Action

If you have any questions, contact your Business Center.