

NUMBER: 18-034-14

GROUP: Vehicle Performance

DATE: June 06, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 14-046. ALL APPLICABLE UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

P0520- Engine Oil Pressure Sensor Circuit

OVERVIEW:

This bulletin involves replacing the oil pressure sensor with a revised part.

MODELS:

| 2013 - 2014 | PF | Dart |
|-------------|----|------------------------------|
| 2013 - 2014 | LD | Charger |
| 2013 - 2014 | LX | 300 |
| 2013 - 2014 | LC | Challenger |
| 2013 - 2014 | JS | 200/Avenger |
| 2013 - 2014 | RT | Town & Country/Grand Caravan |
| 2013 - 2014 | WK | Grand Cherokee |
| 2014 | KL | Cherokee |
| 2013 - 2014 | WD | Durango |
| 2013 - 2014 | DS | Ram 1500 |
| 2013 - 2014 | DJ | Ram 2500 |
| 2013 - 2014 | D2 | Ram 3500 Pickup |
| 2013 - 2014 | DD | Ram 3500 Cab Chassis |
| 2014 | DP | Ram 4500 Cab Chassis |
| 2013 - 2014 | JC | Journey |
| 2013 - 2014 | JK | Wrangler |
| 2014 | VF | ProMaster |
| 2013 - 2014 | ZD | Viper |
| | | |

SYMPTOM/CONDITION:

A small number of customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the Technician may find that the following Diagnostic Trouble Code (DTC) has been set:

• P0520 - Engine Oil Pressure Sensor Circuit

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all engine systems are functioning as designed. If DTC's other then the ones listed above are present, record them on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition or if the technician finds the listed DTC, perform the Repair Procedure.

| Qty. | Part No. | Description | Engine Application |
|------|------------|----------------------|--------------------------------------|
| 1 | 68145662AA | Sensor, Oil Pressure | 2.0L 2.4L |
| 1 | 05149062AA | Sensor, Oil Pressure | 3.0L 3.2L 3.6L 5.7L 6.4L |
| 1 | 05149064AA | Sensor, Oil Pressure | 8.4L |

PARTS REQUIRED:

REPAIR PROCEDURE:

- Replace the oil pressure sensor. Refer to the detailed removal and installation procedure available in DealerCONNECT> Service> TechCONNECT> Service Info> 09
 Engine> Lubrication> Sensor, Oil Pressure> Removal/ Installation.
- 2. Utilizing the wiTECH Diagnostic Application, clear stored DTC's.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

| Labor Operation No: | Description | Skill Category | Amount |
|---------------------|--|------------------------------|----------|
| 08-46-10-92 | Sensor, Oil Pressure - Replace (1 - Semi-Skilled) | 6- Electrical & Body Systems | 0.5 Hrs. |

| | 2.0L/2.4L - PF/KL | | |
|-------------|--|---------------------------------|----------|
| 08-46-10-93 | Sensor, Oil Pressure - Replace (1 - Semi-Skilled) 3.6L - JS/JC | 6- Electrical & Body Systems | 1.0 Hrs. |
| 08-46-10-93 | Sensor, Oil Pressure - Replace (1 - Semi-Skilled) 3.6L - LD/LX/RT | 6- Electrical & Body Systems | 1.2 Hrs. |
| 08-46-10-93 | Sensor, Oil Pressure - Replace (1 - Semi-Skilled) 3.6L - LC | 6- Electrical & Body Systems | 0.9 Hrs. |
| 08-46-10-93 | Sensor, Oil Pressure - Replace (1 - Semi-Skilled) 3.6L - WK/WD | 6- Electrical & Body Systems | 1.3 Hrs. |
| 08-46-10-93 | Sensor, Oil Pressure - Replace (1 - Semi-Skilled) 3.6L - DS | 6- Electrical & Body Systems | 1.6 Hrs. |
| 08-46-10-93 | Sensor, Oil Pressure - Replace (1 - Semi-Skilled) 3.6L - JK | 6- Electrical & Body Systems | 1.7 Hrs. |
| 08-46-10-93 | Sensor, Oil Pressure - Replace (1 - Semi-Skilled) 3.6L - VF | 6- Electrical & Body Systems | 1.8 Hrs. |
| 08-46-10-94 | Sensor, Oil Pressure - Replace (1 - Semi-Skilled) 3.0L - LX | 6- Electrical & Body Systems | 0.9 Hrs. |
| 08-46-10-94 | Sensor, Oil Pressure - Replace (1 - Semi-Skilled) 3.0L - WK | 6- Electrical & Body Systems | 1.3 Hrs. |
| 08-46-10-94 | Sensor, Oil Pressure - Replace (1 - Semi-Skilled) 3.0L - JK | 6- Electrical & Body Systems | 1.7 Hrs. |
| 08-46-10-95 | Sensor, Oil Pressure - Replace (1 - Semi-Skilled) 5.7L/6.4L - DJ/D2/DD/DP/WK/WD | 6- Electrical & Body Systems | 0.4 Hrs. |
| 08-46-10-95 | Sensor, Oil Pressure - Replace (1 - Semi-Skilled) 5.7L/6.4L- LC/LX/LD | 6- Electrical & Body Systems | 0.7 Hrs. |
| 08-46-10-95 | Sensor, Oil Pressure - Replace (1 - Semi-Skilled) 8.4L - ZD | 6- Electrical & Body Systems | 0.3 Hrs. |

FAILURE CODE:

ΖZ