

NUMBER: 22-005-11

GROUP: Tires and wheels

DATE: October 18, 2011

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 11-096. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Chrome Wheel Delamination

OVERVIEW:

This bulletin involves Inspecting and if necessary replacing chrome clad wheels.

MODELS:

2011 (LC) Challenger 2011 (LD) Charger

NOTE: This bulletin applies to all vehicles equipped with (Sales code WPG and WPL Aluminum Chrome Clad Wheels) built after December 4th, 2010 (MDH1204XX) and before February 25th, 2011 (MDH0225XX).

SYMPTOM/CONDITION:

Chrome wheels are delaminating near the valve stems and it looks like a lifting condition.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1 (AR)	1LS64SZ0AA	Wheel, 18x7.5 Chrome Aluminum (Charger Only)
1 (AR)	1NQ47SZ0AA	Wheel, 20x8.0 Chrome Clad Aluminum

22-005-11 -2-

REPAIR PROCEDURE:

1. Inspect all chrome wheels for delamination for signs of delamination (Fig. 1).



Fig. 1 Chrome Wheel

- 1 Delamination
- 2 Valve Stem
- 2. Is the wheel delaminating?
 - a. Yes>> Proceed to Step #3.
 - b. No>>> Return the vehicle to the customer or dealer inventory.
- 3. Remove and return the suspect wheel. Refer to the detailed procedures available in DealerConnect> TechCONNECT under: Service Info> 22- Tires and Wheels> Removal> Tire and Wheel Assembly (Aluminum Wheel).

NOTE: Return the suspect wheel(s) by following the warranty parts return process.

- Mount and Balance the new wheel(s). Refer to the detailed procedures available in DealerConnect> TechCONNECT under: Service Info> 22- Tires and Wheels> Standard Procedure> Tire and Wheel Balance.
- 5. Install the new wheel(s). Refer to the detailed procedures available in DealerConnect> TechCONNECT under: Service Info> 22- Tires and Wheels> Installation> Tire and Wheel Assembly (Aluminum Wheel).

-3- 22-005-11

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
22-40-01-96	Inspect All and Replace One Wheel (X)	0.4 Hrs.
22-40-01-97	Inspect All and Replace Two Wheels (X)	0.6 Hrs.
22-40-01-98	Inspect All and Replace Three Wheels (X)	0.9 Hrs.
22-40-01-99	Inspect All and Replace Four Wheels (X)	1.1 Hrs.
22-40-01-95	Inspect All Four Wheels Only (X)	0.2 Hrs.

FAILURE CODE:

Service Action	ZZ	Service Action
----------------	----	----------------